

NOVA LUCE


9120622




1. Turn off the general switch




2. Untie side screws to break the parts apart




3. Apply screws to make the base stable



4. Place the lamp into the base
& make it stable by tiding up the side screws



5. Turn on the general switch



The working time of the 100% full battery is 5-7 hours.
If on second mode(no PIR sensor), the working time will be around 10 hours.
The charging time is around 8 hours.